W/Al scanning with X2 MAM



Mount the X2 MAM Sensor in the holder.



Place the holder centered on the table, tight to the chest wall.

Always use the compression paddle, positioned as high as possible.

Do **not** use the AEC functionality.

X2 setting: Stop delay 2 s.

