



Information on assessment of compliance with specification

All calibration results at RaySafe are compared with the product's specification, taking the measurement uncertainty into account (with 95% probability). For your product's specification, please refer to your product's manual or raysafe.com.

The tolerance limit for calibration As Left is the specification decreased by the expanded uncertainty of measurement.